

















CITY OF ALBUQUERQUE

August 11, 2015



David Thompson, P.E. Thompson Engineering Consultants, Inc. PO Box 65760 Albuquerque, New Mexico 87193

Re: Assisted Living Center Phase I

Tract 9 Las Lomitas

Request Permanent C.O. – Not Accepted Engineer's Stamp dated: 5-5-15 (D16D101)

Certification dated: 8-6-15

Dear Mr. Thompson,

PO Box 1293

Albuquerque

New Mexico 87103

www.cabq.gov

Based on the Certification received 8/6/2015, Phase 1 is not acceptable for release of Certificate of Occupancy by Hydrology. The following comments must be addressed before a C.O. can be given.

- This plan does not match the approved G&D plan dated 8/7/14. The 8/7/14 plan is the plan to be certified.
- The flows from the northern most parking area should flow toward the parking lot to the south then into a pond and not leave through the entry/exit lane.
- The swale does not match what was approved in the 8/7/14 plan and is not directed toward the side walk culvert.
- The west side of this property was to have a berm, not a little ditch.
- How do you propose to prevent erosion and flooding from the hill on the north side of the building? It appears as though the flows will enter the building.
- When is the infrastructure being placed?
- Provide how erosion and sediment are being contained in the dirt area and not allowed to flow out of the parking curb cut which was not intended to be built with this phase.

If you have any questions, you can contact me at 924-3695 or Rudy Rael at 924-3977.

Rita Harmon, P.E.

Senior Engineer, Hydrology

Planning Department

RR/CC

C:

email