



INSPECTION REPORT

GENERAL INFORMATION

DATE OF INSPECTION: 5/1/2023

PERMITTEE NAME: Mechenbier Construction

PROJECT NAME: Ellison St. Office Warehouse

LOCATION: 4000 Ellison St. NE, Albuquerque, New Mexico, 87109

TRACKING NO: NMR1004C1, NMR1004CM

COMPLIANCE EVALUATION: Unsatisfactory

TYPE OF INSPECTION: 14Day

START TIME: 7:15 PM

END TIME: 7:20 PM

INSPECTOR'S NAME: Jessie Gilliam

INSPECTOR'S TITLE: NPDES Inspector

INSPECTOR'S QUALIFICATIONS: StormwaterONE No: 97d73b46

INSPECTOR'S CONTACT: 505-867-4040

PHASE OF CONSTRUCTION: ☐ Clear and Grub ☒ Excavation ☐ Building (vertical)
☐ Rough Grading ☐ Infrastructure ☐ Final Grading
☐ Final Stabilization ☒ Suspension

WEATHER INFORMATION

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION? ☐ Yes ☒ No

WEATHER AT TIME OF THIS INSPECTION: Clear

TEMPERATURE: 48

HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION? ☐ Yes ☒ No

ARE ANY DISCHARGES OCCURRING NOW? ☐ Yes ☒ No

ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT? ☐ Yes ☒ No

POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

| # | S&E/P2 CONTROLS | MAINTENANCE | CORRECTIVE ACTION | LOCATION | QUANTITY | UNIT | PHOTO |
|---|---------------------------|-------------|-------------------|-----------|----------|------|---------------------|
| 1 | NPDES Permit Notification | None | None | Entrance | 1 | EA | Yes |
| 2 | Construction Entrance | None | None | Entrance | 1 | EA | Yes |
| 3 | Silt Fence | Reset | None | Perimeter | 100 | LF | Yes |
| 4 | Sanilets | Anchor | None | By office | 1 | EA | |

GENERAL SITE INSPECTION ITEMS

| # | INSPECTION ITEM | INSPECTOR'S OBSERVATION | ACTION REQUIRED? | NOTES |
|----|---|---|---|---|
| 1 | Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location? | <input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |
| 2 | Are steep slope areas not actively being worked properly stabilized? | <input type="radio"/> Yes <input type="radio"/> No <input checked="" type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |
| 3 | Are disturbed areas not actively being worked properly stabilized? | <input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |
| 4 | Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs? | <input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |
| 5 | Are discharge points and receiving waters free of any sediment deposits? | <input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |
| 6 | Is trash/litter from work areas collected and placed in covered dumpsters? | <input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |
| 7 | Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained? | <input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |
| 8 | Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material? | <input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A | <input checked="" type="radio"/> Yes <input type="radio"/> No | sanalit is fallen over and needs reset and anchored |
| 9 | Are materials that are potential stormwater contaminants stored inside or in containers? | <input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |
| 10 | Are offsite flows entering the construction site? | <input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |

| # | INSPECTION ITEM | INSPECTOR'S OBSERVATION | ACTION REQUIRED? | NOTES |
|----|---|---|---|--|
| 11 | Is there any evidence that pollutants are leaving the site or are not properly contained on site? | <input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |
| 12 | Are traffic and parking areas restricted so as to reduce soil erosion and dust? | <input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |
| 13 | Are non-stormwater discharges properly controlled? | <input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |
| 14 | Is the project being operated in compliance with the SWPPP and with permit conditions at this time? | <input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A | <input checked="" type="radio"/> Yes <input type="radio"/> No | Need to reset the silt fence along perimeter |
| 15 | Are changes to the SWPPP necessary at this time? | <input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |
| 16 | Are dust control measures being properly implemented? | <input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |
| 17 | Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates) | <input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> N/A | <input type="radio"/> Yes <input checked="" type="radio"/> No | |

CERTIFICATION AND SIGNATURE BY INSPECTOR

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY:

Jessie Gilliam

DATE:

May 01, 2023

SIGNATURE AND AFFILIATION:

Jessie Gilliam

CERTIFICATION AND SIGNATURE BY PERMITTEE

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:

,

DATE:

SIGNATURE: