

#### **INSPECTION REPORT**

# **GENERAL INFORMATION**

DATE OF INSPECTION: 9/5/2023

PERMITTEE NAME: Mechenbier Construction

PROJECT NAME: Ellison St. Office Warehouse

LOCATION: 4000 Ellison St. NE, Albuquerque, New Mexico, 87109

TRACKING NO: NMR1004C1, NMR1004CM

COMPLIANCE EVALUATION: Marginal

TYPE OF INSPECTION: 14Day

START TIME: 8:55 AM

END TIME: 9:05 AM

INSPECTOR'S NAME: Jessie Gilliam

INSPECTOR'S TITLE: NPDES Inspector

INSPECTOR'S QUALIFICATIONS: StormwaterONE No: 97d73b46

**INSPECTOR'S CONTACT:** 505-867-4040

PHASE OF CONSTRUCTION: ☐ Clear and Grub ☐ Excavation ☐ Building (vertical)

■ Rough Grading ■ Infrastructure ■ Final Grading

### **WEATHER INFORMATION**

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?	Yes	<ul><li>No</li></ul>
WEATHER AT TIME OF THIS INSPECTION:	Clear	
TEMPERATURE:	80	
HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?	Yes	<ul><li>No</li></ul>

ARE ANY DISCHARGES OCCURRING NOW?



ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?





# POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	РНОТО
1	NPDES Permit Notification	None	None	Entrance	1	EA	<u>Yes</u>
2	Construction Entrance	None	None	Entrance	1	EA	Yes
3	Silt Fence	None	Re-install	Back perimeter	500	LF	Yes

# **GENERAL SITE INSPECTION ITEMS**

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	• Yes No N/A	Yes No	Sign is posted and visible to the public
2	Are steep slope areas not actively being worked properly stabilized?	Yes No N/A	Yes No	
3	Are disturbed areas not actively being worked properly stabilized?	• Yes ONO ON/A	Yes No	
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	•Yes No N/A	Yes No	
5	Are discharge points and receiving waters free of any sediment deposits?	Yes No N/A	Yes No	
6	Is trash/litter from work areas collected and placed in covered dumpsters?	• Yes • No • N/A	Yes No	
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	• Yes ONO ON/A	Yes No	
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	● Yes ○ No ○ N/A	Yes No	
9	Are materials that are potential stormwater contaminants stored inside or in containers?	• Yes O No O N/A	Yes No	
10	Are offsite flows entering the construction site?	Yes No N/A	Yes No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	Yes ● No N/A	Yes No	No evidence observed leaving the site
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	Yes No N/A	Yes No	
13	Are non-stormwater discharges properly controlled?	• Yes ONo ON/A	Yes No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	Yes ● No N/A	● Yes ○ No	Site is missing silt fence along the back perimeter.
15	Are changes to the SWPPP necessary at this time?	Yes ● No N/A	Yes No	
16	Are dust control measures being properly implemented?	● Yes ○ No ○ N/A	Yes No	
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	● Yes ○ No ○ N/A	Yes No	

# **CERTIFICATION AND SIGNATURE BY INSPECTOR**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY:	Jessie Gilliam	DATE:	September 05, 2023
SIGNATURE AND AFFILIATION:	Jan Day Da.		

# **CERTIFICATION AND SIGNATURE BY PERMITTEE**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:	,	DATE:
SIGNATURE:		