



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Allaso Journal Center</u> <u>7800 Headline Blvd NE, Albuquerque, NM 87109</u>	Inspector:	Kyle Grinold
Permit #:	0781-C D17E107 NMR1003FK	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jul 6, 2021, 2:05:02 PM	Last Rain Event Wednesday, June 30, 2021, 0.14"	Last Precipitation Tuesday, July 6, 2021, 0.16" 48h Forecast --

Inspection Form Instructions

Review each question for this inspection carefully, then answer YES, NO, or N/A (not applicable). If any of the items below are out of compliance, press the "Add Action Item" button above to add a corrective action.

General Information

Inspector's Qualifications

Trained and work experience - see inspector qualification page in section 2 of the SWPPP.

Type of Inspection:

- ☒ **Regular** ☐ During storm event
☐ Post-storm event

Weather Information

Last Storm Event Information

For information on the last storm event, see the weather event information at the end of this inspection.

Weather at time of this inspection?

- ☒ **Clear** ☐ Cloudy ☐ Rain
☐ Sleet ☐ Snowing ☐ High Winds
☐ Partly Cloudy

Have any discharges occurred since the last inspection?

- ☐ Yes ☒ No

If yes, what did the water look like at the time of the discharge?

Are there any discharges at the time of this inspection?

- ☐ Yes ☒ No

If yes, what did the water look like at the time of the discharge?

Is a rain gauge installed on site?

- ☐ Yes ☒ No

If yes, where is it located?

Monitoring nearby gauge and NOAA.

Has the Rain Event Page been filled out?

- ☒ Yes ☐ No



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Allaso Journal Center</u> <u>7800 Headline Blvd NE, Albuquerque, NM 87109</u>	Inspector:	Kyle Grinold
Permit #:	0781-C D17E107 NMR1003FK	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jul 6, 2021, 2:05:02 PM	Last Rain Event Wednesday, June 30, 2021, 0.14"	Last Precipitation Tuesday, July 6, 2021, 0.16" 48h Forecast --

Are there SDS sheets on site?

Yes

No

If yes, where are they located?

Weather events attached to the end of each inspection report. SDS sheets on site with Guzman/ construction trailer south side.

If construction ceases on the site for more than 14 days, the site must be stabilized until construction resumes.

Date Construction Stopped

☐

Date Construction Resumed

☐

Measures Taken to Stabilize the Site:

Construction Phasing

Verify what stage of construction the project is in, and record dates when activities started and were completed.

Installed BMPs

Completed

Started:

03/21

Completed:

03/21

Site Clearing and Grading

Started

Started:

03/21

Completed:

6/21

Installing Utilities

Started

Started:

04/21



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Allaso Journal Center</u> <u>7800 Headline Blvd NE, Albuquerque, NM 87109</u>	Inspector:	Kyle Grinold
Permit #:	0781-C D17E107 NMR1003FK	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jul 6, 2021, 2:05:02 PM	Last Rain Event Wednesday, June 30, 2021, 0.14"	Last Precipitation Tuesday, July 6, 2021, 0.16" 48h Forecast --

Completed:

☐

Building Structure

Started:

☐

Completed:

☐

Paving and Walks

Started:

☐

Completed:

☐

Final Grading/Stabilize Site

Started:

☐

Completed:

☐

Other

Started:

☐

Site-specific BMPs

The corrective actions initiated and date completed are in the Corrective Action Log

List of BMPs Installed:

Security fence with fabric silt fence attached and trenched in place. Fractured rock access pad as designated by the erosion control plan. Port-o-lets. Active watering for dust control. Concrete washout Debris containers

Are all of the above controls installed?

Yes

No

Do any of the above controls need maintenance?

Yes

No

If any of the controls have not been installed or require maintenance, please list the control and explain.

N/A- Site BMPs are congruent with the site activities.



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Allaso Journal Center</u> <u>7800 Headline Blvd NE, Albuquerque, NM 87109</u>	Inspector:	Kyle Grinold
Permit #:	0781-C D17E107 NMR1003FK	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jul 6, 2021, 2:05:02 PM	Last Rain Event Wednesday, June 30, 2021, 0.14"	Last Precipitation Tuesday, July 6, 2021, 0.16" 48h Forecast --

Are the BMPs shown on the map?

☒ Yes☐ No

Were there any changes to the SWPPP?

☐ Yes☒ No

Has the SWPPP been updated?

☐ Yes☒ No

Were the changes to the SWPPP implemented within 7 days?

☐ Yes☒ No

List any new BMPs needed:

No additional BMPs required at this time.
No changes to the SWPPP document.

Notes:

Oversight Issues

A list of corrective actions will be supplied with this inspection.

1. Are all slopes and disturbed areas not actively being worked properly stabilized?

Implemented?

☒ Yes☐ No☐ N/A

Maintenance Required?

☐ Yes☒ No☐ N/A

2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?

Implemented?

☒ Yes☐ No☐ N/A

Maintenance Required?

☐ Yes☒ No☐ N/A

3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?

Implemented?

☒ Yes☐ No☐ N/A

Maintenance Required?

☐ Yes☒ No☐ N/A

4. Are discharge points and receiving waters free of any sediment deposits?



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Allaso Journal Center</u> <u>7800 Headline Blvd NE, Albuquerque, NM 87109</u>	Inspector:	Kyle Grinold
Permit #:	0781-C D17E107 NMR1003FK	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jul 6, 2021, 2:05:02 PM	Last Rain Event Wednesday, June 30, 2021, 0.14"	Last Precipitation Tuesday, July 6, 2021, 0.16" 48h Forecast --

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

5. Are storm drain inlets properly protected?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

6. Is the construction exit preventing sediment from being tracked into the street?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

7. Is trash/litter from work areas collected and placed in dumpsters?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

8. Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

9. Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required

Yes	No	N/A
-----	----	-----

10. Are materials that are potential storm water contaminants stored inside or under cover?



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Allaso Journal Center</u> <u>7800 Headline Blvd NE, Albuquerque, NM 87109</u>	Inspector:	Kyle Grinold
Permit #:	0781-C D17E107 NMR1003FK	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jul 6, 2021, 2:05:02 PM	Last Rain Event Wednesday, June 30, 2021, 0.14"	Last Precipitation Tuesday, July 6, 2021, 0.16" 48h Forecast --

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

11. Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

12. Has the Site map been updated to reflect current conditions?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

13. Is the NOI posted?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

14. Were previous corrections made within 7 days of last inspection or before the next storm event?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

Are there any signs of hazardous materials being exposed to storm water runoff?

Yes	No
-----	----

Have there been any reportable quantities releases of hazardous materials?

Yes	No
-----	----



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Allaso Journal Center</u> <u>7800 Headline Blvd NE, Albuquerque, NM 87109</u>	Inspector:	Kyle Grinold
Permit #:	0781-C D17E107 NMR1003FK	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jul 6, 2021, 2:05:02 PM	Last Rain Event Wednesday, June 30, 2021, 0.14"	Last Precipitation Tuesday, July 6, 2021, 0.16" 48h Forecast --

Additional Notes

Site is clean and organized. No site corrective actions at the time of inspection.

Certification & Signatures

Certification Statement:

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Electronic Signature

X *Kyle Grinold*

Date
July 6, 2021 at 2:05:38 PM MDT

Title
Inspector



INSPECTIONS PLUS


General Permit SWPPP Inspection

Site Name:	Allaso Journal Center 7800 Headline Blvd NE, Albuquerque, NM 87109	Inspector:	Kyle Grinold
Permit #:	0781-C D17E107 NMR1003FK	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jul 6, 2021, 2:05:02 PM	Last Rain Event Wednesday, June 30, 2021, 0.14"	Last Precipitation Tuesday, July 6, 2021, 0.16" 48h Forecast --

Weather History

 Precipitation Recorded  No Precipitation  Missed or data unavailable

June



July



All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Allaso Journal Center</u> <u>7800 Headline Blvd NE, Albuquerque, NM 87109</u>	Inspector:	Kyle Grinold
Permit #:	0781-C D17E107 NMR1003FK	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jul 6, 2021, 2:05:02 PM	Last Rain Event Wednesday, June 30, 2021, 0.14"	Last Precipitation Tuesday, July 6, 2021, 0.16"
			48h Forecast --

There Are No Action Items