



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	D17E112	Project Name:	Allaso JC-Six Apartments		
NPDES Id. No.	NMR1005DB	Location:	7501 Jefferson St. NE		
10/23/2023	Owner		Contractor		
Operator	Titan JC6 LLC		HB Construction		
Contact name & title	Josh Rogers		Zach Gruen		
e-mail	jrogers@titan-development.com		zachg@hbconstruction.com		
Contact Phone #	505-998-0163		505-856-0404		
COA Inspector	Chancellor English		Start/End Time:	3pm	
Construction Phase:	Vertical				
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input checked="" type="checkbox"/> Follow Up
Weather at time of inspection?	Clear		Temperature: ~	75	
Estimated date of last storm 0.25" or greater	9/14/2023				

Item Number	Deficiency/ Corrective Action				
1	None				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Via email	Latest report Date:	10/16/2023	

Notes:	
Inspections Plus will add the City to the emailed circulation of self-inspection reports. Previous violations have been mitigated.	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Chancellor English (505) 924-3325
cenglish@cabq.gov