



# City of Albuquerque Stormwater Construction Site Inspection Report

General Information					
ESC File No.	D17E112		Project Name:	Allaso JC-Six Apartments	
NPDES Id. No.	NMRI005DB		Location:	7501 Jefferson St. NE	
6/24/2024	Owner		Contractor		
Operator	Titan JC6 LLC		HB Construction		
Contact name & title	Josh Rogers		Zach Gruen		
e-mail	<a href="mailto:jrogers@titan-development.com">jrogers@titan-development.com</a>		<a href="mailto:zachg@hbconstruction.com">zachg@hbconstruction.com</a>		
Contact Phone #	505-998-0163		505-856-0404		
COA Inspector	Chancellor English		Start/End Time:	1pm	
Construction Phase:	Vertical				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up
Weather at time of inspection?	Clear		Temperature: ~	100	
Estimated date of last storm 0.25" or greater	6/10/2024				
Item Number	Deficiency/ Corrective Action				
1	None				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Yes	Latest report Date:	6/11/2024	
Notes:					

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Chancellor English (505) 924-3325  
[cenglish@cabq.gov](mailto:cenglish@cabq.gov)

\_\_\_\_\_