

INSPECTION REPORT

GENERAL INFORMATION

| DATE OF INSPECTION: | 6/8/2020 | | |
|--------------------------------------|--|--|--|
| COMPANY NAME: | PWKI, LLC | | |
| PROJECT NAME: | Hope Christian Elementary School | | |
| LOCATION: | 6721 Palomas Ave. NE,Albuquerque,New Mexico,87109 | | |
| TRACKING NO: | NMR1002KU | | |
| COMPLIANCE EVALUATION: | Satisfactory | | |
| TYPE OF INSPECTION: | 14Day | | |
| START TIME: | 8:30 AM | | |
| END TIME: | 8:50 AM | | |
| INSPECTOR'S NAME: | Diana Baltazar | | |
| INSPECTOR'S TITLE: | NPDES Inspector | | |
| INSPECTOR'S QUALIFICATIONS: | StormwaterONE No: 6f93e116 | | |
| INSPECTOR'S CONTACT: | 505-379-2445 | | |
| PHASE OF CONSTRUCTION: | Clear and Grub ☐ Excavation ✓ Building (vertical)☐ Rough Grading ☐ Infrastructure ☐ Final Grading☐ Final Stabilization | | |
| WEA | THER INFORMATION | | |
| HAS A STORM EVENT OCCURRED SINCE THE | | | |

| LAST INSPECTION? | O Yes | No |
|---|-------|----------------------|
| WEATHER AT TIME OF THIS INSPECTION: | Clear | |
| TEMPERATURE: | 71 | |
| HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION? | Yes | No |
| ARE ANY DISCHARGES OCCURRING NOW? | Yes | No |
| ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT? | Yes | No |

POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

| # | S&E/P2 CONTROLS | MAINTENANCE | CORRECTIVE ACTION | LOCATION | QUANTITY | UNIT | рното |
|---|--------------------------|-------------|----------------------|-----------------------------|----------|------|-------|
| 1 | Construction Entrance | None | None | Palomas Ave. Ne Entrance | 1 | EA | Yes |
| 2 | Silt Fence | None | None | Perimeter | 1350 | LF | Yes |

GENERAL SITE INSPECTION ITEMS

| # | INSPECTION ITEM | INSPECTOR'S OBSERVATION | ACTION REQUIRED? | NOTES |
|----|--|----------------------------|------------------|--|
| 1 | Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location? | • Yes ONo ON/A | Yes No | Sign is correctly displayed at entrance. |
| 2 | Are steep slope areas not actively being worked properly stabilized? | Yes No N/A | Yes No | |
| 3 | Are disturbed areas not actively being worked properly stabilized? | ● Yes ○ No ○ N/A | Yes No | Areas are currently being worked on. |
| 4 | Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs? | ● Yes ○ No ○ N/A | Yes No | Silt fence and wattles are intact and containing sediment on site. |
| 5 | Are discharge points and receiving waters free of any sediment deposits? | • Yes ONo ON/A | Yes No | |
| 6 | Is trash/litter from work areas collected and placed in covered dumpsters? | ● Yes ○ No ○ N/A | Yes No | Dumpsters on site, site is clean and clear |
| 7 | Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained? | ● Yes ○ No ○ N/A | Yes No | |
| 8 | Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material? | ● Yes ○ No ○ N/A | Yes No | |
| 9 | Are materials that are potential stormwater contaminants stored inside or in containers? | • Yes ONo ON/A | Yes No | |
| 10 | Are offsite flows entering the construction site? | Yes ● No N/A | Yes No | |
| 11 | Is there any evidence that pollutants are leaving the site or are not properly contained on site? | Yes ● No N/A | Yes No | |

| # | INSPECTION ITEM | INSPECTOR'S OBSERVATION | ACTION REQUIRED? | NOTES |
|----|---|----------------------------|------------------|-------|
| 12 | Are traffic and parking areas restricted so as to reduce soil erosion and dust? | ● Yes ○ No ○ N/A | ○Yes • No | |
| 13 | Are non-stormwater discharges properly controlled? | ● Yes ○ No ○ N/A | ◯ Yes ● No | |
| 14 | Is the project being operated in compliance with the SWPPP and with permit conditions at this time? | • Yes ONo ON/A | ◯ Yes ● No | |
| 15 | Are changes to the SWPPP necessary at this time? | ○ Yes ● No ○ N/A | ◯ Yes ● No | |
| 16 | Are dust control measures being properly implemented? | ● Yes ○ No ○ N/A | ◯ Yes ● No | |
| 17 | Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates) | ● Yes ○ No ○ N/A | ○Yes ● No | |

CERTIFICATION AND SIGNATURE BY INSPECTOR

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

| INSPECTED BY: | Diana Baltazar | DATE: | June 09, 2020 |
|---------------|----------------|-------|---------------|
|---------------|----------------|-------|---------------|

SIGNATURE AND AFFILIATION:

CERTIFICATION AND SIGNATURE BY PERMITTEE

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

| PRINT NAME AND TITLE: | , | DATE: |
|-----------------------|---|-------|
| SIGNATURE: | | |