



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Santa Monica Estates II				
Location:	Brentwood Blvd & Santa Monica				
Site Contact Name & Agency	Brian Patterson - 980-1650	ESC File No.	D18E054E		
	bpatterson@titan-development.com	NPDES Id. No.	NMR100105		
Inspection Date:	09/11/19	Start/End Time:	1210/1220hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	pad certification				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	85*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 9/10/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 09/11/19