



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Santa Monica Estates II		
Location:	Brentwood Blvd & Santa Monica		
Site Contact Name & Agency	Stillbrooke Homes ckelsey@stillbrooke.com	ESC File No.	D18E054F_S
		NPDES Id. No.	NMR100105
Inspection Date:	01/27/20	Start/End Time:	1000/1045hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	home construction		
Type of Inspection:	☐ Regular	☐ Storm Event	☐ Post Storm Event >0.25" ☒ 311/Complaint ☒ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	45*
Estimated date of last storm 0.25" or greater	11/7/2019		

Item Number	Deficiency/ Corrective Action		
	all previous issues mitigated, no new issues observed		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requestes	Latest report Date: 11/11/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 01/27/20