



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Santa Monica Estates				
Location:	Brentwood Blvd. & Santa Monica				
Site Contact Name & Agency	Chris Kelsey - 350-0493 ckelsey@stillbrooke.com	ESC File No.	D18E054F_S & A		
		NPDES Id. No.			
Inspection Date:	08/01/19	Start/End Time:	1220/1300hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	home construction				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	90*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
	Please provide the latest SWPPP self-inspection report		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 5/28/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 08/01/19