

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Nar	ne:	Santa Monica Estates II					
Location:		Brentwood Blvd & Santa Monica					
Site Contact Name &		Abrazo Homes ESC File N			D18E054E_A		
Agency		chris@abraz	zohoomes.com	NPDES Id. No.		_	
Inspection Date:		01/15/20 S	start/End Time: 07	730/074hrs			•
	water Inspector		imothy E. Sims	•			
	ction Phase:	i i		home co	nstruction		
Type of In	spection: X	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	Follow Up
, ·							
Weather at time of inspection? Clear Temperature: ~							31*
Estimated	date of last s	torm 0.25" or greater			11/27/2019		
la oues							
Item	Deficiency/ Corrective Action						
Number							
1	Please provide	NPDES postir	ng of the site.				
2	Please provide approval of the ESC plan to City Storm Water Quality program.						
3	Domestic and Construction waste not in acceptable container. Please clean and use the provided						
	refuse containers.						
4	Washouts not in acceptable washout container or facility. Please mitigate and prevent in the future.						
5	Please provide the latest SWPPP self-inspection report.						
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	tion Reports	requested	Latest rep	ort Date:	11/11/2	019
					I		
Notes:							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

01/15/20\_\_\_\_\_