



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	D18E054F_A	Project Name:	Santa Monica Estates		
NPDES Id. No.	NMR10009C	Location:	San Vicente Ave. and Brentwood Blvd. NE		
Owner		Contractor			
Operator	TQM, LLC.				
Contact name & title	Chris Myers				
e-mail	chris@abrazohomes.com				
Contact Phone #	505-796-6119				
COA Inspector	Thomas Evans		Start/End Time:	2:05 PM/2:10 PM	
Construction Phase:	Completed				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Past Storm Event >0.25"	<input type="checkbox"/> 311/Complaint <input type="checkbox"/> Follow Up	
Weather at time of inspection?		Clear	Temperature: ~	73	
Estimated date of last storm 0.25" or greater		2/22/2021			
Item Number	Deficiency/ Corrective Action				
1	None. Site completed				
2					
3					
4					
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports		Latest report Date:	4/13/2020	

Notes:	All homes completed.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 04/14/2021