



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Santa Monica Estates II				
Location:	Brentwood Blvd & Santa Monica				
Site Contact Name & Agency	Abrazo Homes (TQMLLC)	ESC File No.	D18E054F_A		
	chris@abrazohomes.com	NPDES Id. No.	NMR10009C		
Inspection Date:	04/23/20	Start/End Time:	1000/1015hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	home construction				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	56*
Estimated date of last storm 0.25" or greater	4/13/2020		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection.		
	***Please provide the latest SWPPP self-inspection report.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 3/30/2020

Notes:	Extensive efforts are mitigating concrete washouts and sediment in streets.- Good

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 04/23/20