

City of Albuquerque Stormwater Construction Site Inspection Report

General Information											
Project Nar	me:	Santa Monica Estates II									
Location:		Brentwood Blvd & Santa Monica									
Site Contact Name &		Stillbrooke Homes ESC File No.				D18E054E					
Agency			ckelsey@stillbrooke.com NPDES Id. N		NMR100105						
Inspection Date:				730/074hrs							
	water Inspecto										
Construction Phase:		home construction									
Type of Ir	nspection: X	Regular	Storm Event	Post Storm E	Event >0.25"	311/Complaint	Follow Up				
Weath	or at time of i	nenaction?	Cle	ar	Tompo	erature: ~	31*				
Weather at time of i Estimated date of last s		torm 0.25" o	r greater		Tempe	11/27/2019	51				
Item	Deficiency/ Corrective Action										
Number											
1	Please provide NPDES posting for this site. The NPDES posting is missing, please repost.										
2	Domestic and Construction waste not in acceptable container. Please clean and use the provided										
	refuse containers.										
3	Washouts not in acceptable washout container or faciilty. Please mitigate and prevent in the future.										
4	Please provide the latest SWPPP self-inspection report.										
2.1	Discharge off site?	(Y/N)	No								
4	÷	tion Reports	requested	Latest rec	oort Date:	11/11/2	019				
L											

Notes:			

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155