

## City of Albuquerque Stormwater Construction Site Inspection Report

	18E054F_S		
Location:Brentwood Blvd & Santa MonicaSite Contact Name &Stillbrooke HomesESC File No.D			
Site Contact Name & Stillbrooke Homes ESC File No. D			
Agency ckelsey@stillbrooke.com NPDES Id. No. N	NMR100105		
Agency Ckelsey@stillbrooke.com NPDES Id. No. N   Inspection Date: 01/22/20 Start/End Time: 1015/1030hrs			
CoA Stormwater Inspector: Timothy E. Sims			
Construction Phase: home construction			
	,,		
Weather at time of inspection? Clear Temperature: ~ 45*			
Estimated date of last storm 0.25" or greater	11/7/2019		
Item			
Deficiency/ Corrective Action	Deficiency/ Corrective Action		
Number			
1 all previous issues mitigated,	all previous issues mitigated,		
NEW			
1 Too much sediment is in the streets. Please mitigate and prevent in the futur	much sediment is in the streets. Please mitigate and prevent in the future		
this requires mitigation within seven days.			
2.1 Discharge off site? (Y/N) NO			
4 Self Inspection Reports Latest report Date:	11/11/2019		

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155