



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Santa Monica Estates II				
Location:	Brentwood Blvd & Santa Monica				
Site Contact Name & Agency	Stillbrooke Homes	ESC File No.	D18E054F_S		
	ckelsey@stillbrooke.com	NPDES Id. No.	NMR100105		
Inspection Date:	03/31/20	Start/End Time:	1100/1130hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	home construction				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	56*
Estimated date of last storm 0.25" or greater	11/7/2019		

Item Number	Deficiency/ Corrective Action			
	no issues observed with this inspection			
	***Please provide latest SWPPP self-inspection report.			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	11/11/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 03/31/20