



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

ESC File No.	D18E054F_SB	Project Name:	Santa Monica Estates		
NPDES Id. No.	NMR10014N	Location:	San Vicente Ave. and Brentwood Blvd. NE		
Owner		Contractor			
Operator	Stillbrooke Homes				
Contact name & title	Chris Kelsey				
e-mail	<a href="mailto:ckelsey@stillbrooke.com">ckelsey@stillbrooke.com</a>				
Contact Phone #	505-923-4619				
COA Inspector	Thomas Evans		Start/End Time:	2:05 PM/2:10 PM	
Construction Phase:	Completed				
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"	311/Complaint Follow Up	
Weather at time of inspection?		Clear	Temperature: ~	73	
Estimated date of last storm 0.25" or greater		2/22/2021			

Item Number	Deficiency/ Corrective Action			
1	None. Site completed			
2				
3				
4				
5				
2.1	Discharge off site? (Y/N)	no		
4	Self Inspection Reports		Latest report Date:	4/21/2020

Notes:	All homes completed.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)  
[tevans@cabq.gov](mailto:tevans@cabq.gov)

*Thomas Evans* 04/14/2021