



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Santa Monica Estates				
Location:	Brentwood and Santa Monica				
Site Contact Name & Agency	Chris Kelsey	ESC File No.	D18E054F		
	Stillbrooke Homes	NPDES Id. No.			
Inspection Date:	06/14/19	Start/End Time:	7:45/7:50		
CoA Stormwater Inspector:	Curtis Cherne				
Construction Phase:	Constructing two homes				
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input checked="" type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	75
Estimated date of last storm 0.25" or greater	5/10/2019		

Item Number	Deficiency/ Corrective Action		
	This morning's inspection was a brief follow-up from the inspection/meeting that occurred on the afternoon of 6-13-19		
1	Construction wastes that were piled in the front yard of the two homes had been removed as stated by Chris, except there were hundreds/thousands of small pieces of sheetrock remaining. This is one of the issues with throwing sheetrock in the front yard.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 5/28/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Curtis Cherne PE, 505-924-3420
ccherne@cabq.gov

06/14/19