



City of Albuquerque Stormwater Construction Site Inspection Report

General Information					
Project Name:	Presbyterian San Pedro				
Location:					
Site Contact Name & Agency	Jaynes Jan Nakotte	ESC File No.	D18E056		
		NPDES Id. No.			
Inspection Date:	04/09/19	Start/End Time:	1030/1100hrs		
CoA Stormwater Inspector:	Timothy Sims, Stormwater Inspector				
Construction Phase:	Stabilized				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	68°
Has there been a storm event since site was Permitted?			
Clarify amount: (i.e.. <1/4" to >3/4"): yes, >1/4"			

Item Number	Deficiency/ Corrective Action		
	SITE IS STABILIZED		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	N/A	Latest report Date:

Notes: (City Inspector Use) Items in compliance can be left blank.

¹ Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy Sims, 505-803-6155 or
tsims@cabq.gov

04/09/19