

## **INSPECTION REPORT**

## **GENERAL INFORMATION**

DATE OF INSPECTION:	9/30/2019		
COMPANY NAME:	Pavilion Construction, LLC		
PROJECT NAME:	Overture		
LOCATION:	6442 Palomas Ave NE, Albuquerque, New Mexico, 87109		
TRACKING NO:	NMR1001QG		
COMPLIANCE EVALUATION:	Marginal		
TYPE OF INSPECTION:	14Day		
START TIME:	8:55 AM		
END TIME:	9:20 AM		
INSPECTOR'S NAME:	Diana Baltazar		
INSPECTOR'S TITLE:	NPDES Inspector		
INSPECTOR'S QUALIFICATIONS:	StormwaterONE No: 6f93e116		
INSPECTOR'S CONTACT:	505-379-2445		
PHASE OF CONSTRUCTION:	<ul> <li>□ Clear and Grub □ Excavation ✓ Building (vertical)</li> <li>□ Rough Grading □ Infrastructure □ Final Grading</li> <li>□ Final Stabilization</li> </ul>		
WEATHER INFORMATION			

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?	Yes	<ul><li>No</li></ul>
WEATHER AT TIME OF THIS INSPECTION:	Clear	
TEMPERATURE:	68	
HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?	Yes	<ul><li>No</li></ul>
ARE ANY DISCHARGES OCCURRING NOW?	Yes	<ul><li>No</li></ul>
ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?	Yes	<ul><li>No</li></ul>

# POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	РНОТО
1	NPDES Permit Notification	None	None	Palomas Ave. Entrance	1	EA	Yes
2	Construction Entrance	Clean	None	Palomas Ave. Entrance	1	EA	Yes
3	Silt Fence	None	None	Perimeter	1700	LF	
4	Inlet Protection	None	None	Around perimeter	4	EA	Yes
5	Sediment Track Out	Clean	None	Entrance	1	HR	Yes

## **GENERAL SITE INSPECTION ITEMS**

		INSPECTOR'S		
#	INSPECTION ITEM	OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	● Yes ○ No ○ N/A	○Yes • No	
2	Are steep slope areas not actively being worked properly stabilized?	Yes ○No ●N/A	Yes No	
3	Are disturbed areas not actively being worked properly stabilized?	Yes No N/A	Yes No	Areas have been compacted due to construction traffic.
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	● Yes ○ No ○ N/A	● Yes ○ No	Sediment track out should be cleaned and swept. Construction entrance should be cleaned.
5	Are discharge points and receiving waters free of any sediment deposits?	●Yes ○No ○N/A	• Yes No	Sediment has rescheduled site SD inlets, which came from construction entrance.
6	Is trash/litter from work areas collected and placed in covered dumpsters?	● Yes ○ No ○ N/A	● Yes ○ No	Trash and debris to be cleaned by end of day, crews were working on clean up during inspection.
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	● Yes ○ No ○ N/A	• Yes No	CW should be cleaned, currently over flowing with concrete debris that is running off site.
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	● Yes ○ No ○ N/A	Yes No	_

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
9	Are materials that are potential stormwater contaminants stored inside or in containers?	• Yes ONO N/A	Yes No	
10	Are offsite flows entering the construction site?	○ Yes ● No ○ N/A	Yes No	
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	Yes ● No N/A	• Yes No	Concrete washout station over flown
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	Yes No N/A	Yes No	
13	Are non-stormwater discharges properly controlled?	• Yes ONo ON/A	Yes No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	• Yes ONo ON/A	Yes No	
15	Are changes to the SWPPP necessary at this time?	○ Yes ● No ○ N/A	Yes No	
16	Are dust control measures being properly implemented?	• Yes ONo ON/A	Yes No	
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	● Yes ○ No ○ N/A	Yes No	

#### **CERTIFICATION AND SIGNATURE BY INSPECTOR**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY:	Diana Baltazar	DATE:	October 01, 2019
---------------	----------------	-------	------------------

### SIGNATURE AND AFFILIATION:

### **CERTIFICATION AND SIGNATURE BY PERMITTEE**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:	DATE:

