

INSPECTION REPORT

GENERAL INFORMATION

DATE OF INSPECTION:	2/17/2020
COMPANY NAME:	Pavilion Construction, LLC
PROJECT NAME:	Overture
LOCATION:	6442 Palomas Ave NE, Albuquerque, New Mexico, 87109
TRACKING NO:	NMR1001QG
COMPLIANCE EVALUATION:	Satisfactory
TYPE OF INSPECTION:	14Day
START TIME:	9:45 AM
END TIME:	10:05 AM
INSPECTOR'S NAME:	Diana Baltazar
INSPECTOR'S TITLE:	NPDES Inspector
INSPECTOR'S QUALIFICATIONS:	StormwaterONE No: 6f93e116
INSPECTOR'S CONTACT:	505-379-2445
PHASE OF CONSTRUCTION:	Clear and Grub ☐ Excavation ✓ Building (vertical)Rough Grading ☐ Infrastructure ☐ Final GradingFinal Stabilization

WEATHER INFORMATION

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?

Yes
No

Snow Event IF YES, PROVIDE:

# STORM DATE		STORM DATE ESTIMATED STORM DURATION (HOURS)		
1	2/11/2020	6	0.15	

WEATHER AT TIME OF THIS INSPECTION: Clear

43 **TEMPERATURE:**

HAVE ANY DISCHARGES OCCURRED SINCE	
THE LAST INSPECTION?	
ARE ANY DISCHARGES OCCURRING NOW?	

ARE	ANY	PORTIONS	OF	YOUR	SITE	UNSAF	E

TO INSPECT?

○ Yes	● No
Yes	No

Yes No

POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	РНОТО
1	NPDES Permit Notification	None	None	Palomas Ave. Entrance	1	EA	Yes
2	Construction Entrance	None	None	Palomas Ave. Entrance	1	EA	Yes
3	Silt Fence	None	None	Perimeter	100	EA	Yes

GENERAL SITE INSPECTION ITEMS

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	• Yes O No O N/A	○Yes	0.15 in collected from rain gauge
2	Are steep slope areas not actively being worked properly stabilized?	Yes No N/A	Yes No	
3	Are disturbed areas not actively being worked properly stabilized?	• Yes ONo ON/A	Yes No	Areas are compacted throughout roadways.
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	• Yes O No O N/A	Yes No	All storm water inlets are plugged with liner, monitor liner for sediment build up.
5	Are discharge points and receiving waters free of any sediment deposits?	• Yes ONo ON/A	Yes No	
6	Is trash/litter from work areas collected and placed in covered dumpsters?	● Yes ○ No ○ N/A	Yes No	Dumpsters on site, site to be cleaned by end of each day.
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	● Yes ○ No ○ N/A	Yes No	Washout in use.
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	• Yes O No O N/A	Yes No	Areas that have caused leaks mostly from non-potable water are protected by wattles.

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
9	Are materials that are potential stormwater contaminants stored inside or in containers?	• Yes ONO N/A	◯ Yes ● No	
10	Are offsite flows entering the construction site?	Yes No N/A	☐ Yes ● No	
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	Yes ● No N/A	☐ Yes ● No	
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	Yes No N/A	• Yes No	Sweeping should be done at areas that traffic is using to access yard.
13	Are non-stormwater discharges properly controlled?	Yes No N/A	○Yes ● No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	• Yes ONo ON/A	○Yes ● No	
15	Are changes to the SWPPP necessary at this time?	○ Yes ● No ○ N/A	◯ Yes ● No	
16	Are dust control measures being properly implemented?	• Yes ONo ON/A	◯ Yes ● No	
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	• Yes ONo ON/A	○Yes	

CERTIFICATION AND SIGNATURE BY INSPECTOR

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY: Diana Baltazar	DATE:	February	17, 20	ე20
------------------------------	-------	----------	--------	-----

SIGNATURE AND AFFILIATION:

CERTIFICATION AND SIGNATURE BY PERMITTEE

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:	DATE

