

## City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:		Palomas Peak Office Development					
Location:		8310Palomas NE					
Site Contact Name & Agency		Steven - Trinity		ESC File No.		D19E031	
		steven@trinitynm.co		NPDES Id. No.		NMR1002QI	
Inspection Date:		02/18/20		Start/End Time:		1030/1055hrs	
CoA Stormwater Inspector:		Timothy E. Sims					
Construction Phase:		earthwork					
Type of Inspection:	x	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up	

Weather at time of inspection?	Clear	Temperature: ~	46*
Estimated date of last storm 0.25" or greater			

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
	***Please forward me the latest SWPPP self-inspection report.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: not on file

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 02/18/20