



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Palomas Peak Office Development				
Location:	8310Palomas NE				
Site Contact Name & Agency	Steven - Trinity	ESC File No.	D19E031		
	steven@trinitynm.co	NPDES Id. No.	NMR1002QI		
Inspection Date:	05/18/20	Start/End Time:	1045/1115hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	vertical				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	81*
Estimated date of last storm 0.25" or greater	4/13/2020		

Item Number	Deficiency/ Corrective Action			
	no issues observed with this inspection			
	***Please forward me the latest SWPPP self-inspection report.			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	3/2/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 05/18/20