



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	D19E031	Project Name:	Palomas Peak Phase 2		
NPDES Id. No.	NMR1002Q1	Location:	8310 Palomas Ave. NE		
4/10/2023	Owner	Contractor			
Operator	Palomas Peak, LLC	Trinity			
Contact name & title	Eric Tidmore	Chuck Wilkins			
e-mail	eric@trinitynm.com	chuck@trinitynm.com			
Contact Phone #	505-830-1928	505-850-4505			
COA Inspector	Doug Hughes	Start/End Time:	2pm		
Construction Phase:	Stabile & Occupied				
Type of Inspection:		Storm Event	Past Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?	clear		Temperature:	~	78
Estimated date of last storm 0.25" or greater	3/16/2023				
Item Number	Deficiency/ Corrective Action				
1	None.				
	The Final Stabilization Criteria CGP2.2.14.c has been satisfied. Now you must send documentation of the Final Stabilization to the EPA with a Notice of Termination (NOT) per CGP 8.2 to end your coverage under the CGP. This step is independent of the Certificate of Occupancy. Please copy me with the documentation and the EPA's acceptance of the NOT.				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:		

Notes:	Permit Coverage is expired - file NOT anyway.

City of Albuquerque Stormwater Inspector Signature and date:
 Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov
