## CITY OF ALBUQUERQUE

January 19, 2018

Gerald Hamilton, 3HN Healthcare Properties, beehiveabq@aol.com

Site: Beehive Montano

Re: Drainage Ordinance (14-5-2-1) Violations for Erosion and Sediment Control

Dear Mr. Hamilton,

The following violations were observed at yesterday's inspection.

- 1. Track-out pad in poor condition.
- 2. Track-out, sediment and wood debris on Montano Road.

Photos are shown below:



Albuquerque

PO Box 1293

NM 87103

www.cabq.gov

Track-out pad in poor condition.



CITY OF ALBUQUERQUE



Track-out and wood debris on Montano Road.

PO Box 1293

## Required Mitigation:

Albuquerque

- 1. Install a new track-out pad with filter fabric per approved Erosion and Sediment Control Plan.
- 2. Remove sediment and wood debris from Montano Road.

NM 87103

If violations are not mitigated within 30 days, the property owner is subject to a fine of \$500/day per the City's Drainage Control Ordinance.

www.cabq.gov

If you would like to schedule a follow-up inspection at a day and time of your convenience, prior to 30 days from the date of this letter please let me know.

If you have any questions, you can contact me at 924-3420.

Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality

Planning Dept.