



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:	Guardian Storage				
Location:	3600 Bosque Plaza Lan NW				
Site Contact Name & Agency	Paul Hedges <a href="mailto:pdhedges@hotmail.com">pdhedges@hotmail.com</a>	ESC File No.	E12E006E		
		NPDES Id. No.	NMR100110K		
Inspection Date:	05/06/19	Start/End Time:	1345/1350hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	Idol				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	81*
Estimated date of last storm 0.25" or greater	4/22/2019		

Item Number	Deficiency/ Corrective Action		
	no issues noted		
	site is idol		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date:

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 05/06/19