City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Guardian Storage						
Location:	3600 Bosque Plaza Lan NW						
Site Contact Name & Agency	Paul Hedges			ESC File No.	E12E006E		
	pdhedges@hotmail.com			NPDES Id. No.	NMR100110K		
Inspection Date:	06/20/19	Start/End Time:	0930/0935hrs				
CoA Stormwater Inspector:	Timothy E. Sims						
Construction Phase:	STABILIZED						
Type of Inspection:	x Regular	Storm Event		Post Storm Event >0.25"		311/Complaint	Follow Up

Weather at time of inspection?	Clear	Temperature: ~	80*
Estimated date of last storm 0.25" or greater		5/11/2019	

Item Number	Deficiency/ Corrective Action		
	STABILIZED		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date:

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: Timothy E. Sims

Digitally signed by Timothy E. Sims
DN: cn=Timothy E. Sims, o=Stormwater Inspectionos, ou=Planning, email=tsims@cabq.gov, c=US
Date: 2019.06.20 11:53:24 -06'00'

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov 06/20/19