

## City of Albuquerque Stormwater Construction Site Inspection Report

			General Information			
Project Name and Location		Guardian Arrage 3600 Bosque Plaza Lane				
Site Contact Name & Agency		Paul Hedger Guardian Sterage		ESC File No. NPDES ID No.	E12 EOOGE NMRIOUIOK	
Date of Inspection		2-4-19		Start/End 1:1	0/2:00	
COA Inspector Name		Curtis Cherne, Stormwater Quality				
Describe Present Phase of Construction		powis slot, extern of 6/89				
Type of I	-	nevent • Post-	storm event (> 0.25 inch)	311 / Complaint Res	sponse Follow-Up	
		State was to a state of	Weather Information			
	at time of this inspection		Fog · Snowing ·	Ten Windy	nperature: ~_60_F°	
	• e been a storm event sin		rmitted? Yes No"			
			Inspection			
CGP <sup>1</sup> Section	Maintenance or Corrective Action Required		Location and Notes			
1.5	Post a Notice					
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft	/				
2.2.3	Sediment control along any perimeter	V	gaps in silt	Since wint	v Sile	
2.2.3	Sediment control along any perimeter		Soft fuce requ	ins Mainterano	e north side	
2.2.3	Sediment control along any perimeter		Track-out into	La orilla		
2.2.3	Sediment control along any perimeter		spained in La	orilla		
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.4	Minimize sediment track-		no track			

2.2.5	Manage stockpiles					
2.2.6	Minimize Dust					
2.2.10	Protect Storm Drain Inlets					
2.2.10	Protect Storm Drain Inlets					
2.2.11	Minimize erosion of conveyance channels					
2.2.12	Sediment Basins	=				
2.2.14	Stabilize exposed portions of the site.					
2.2.14	Stabilize exposed portions of the site.					
2.2.14	Stabilize exposed portions of the site.					
2.2.14	Stabilize exposed portions of the site.					
2.3.1	Equipment and Vehicle Fueling					
2.3.2	Equipment and Vehicle Washing					
2.3.3	Building Material Storage					
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage	/	oil dripper in Le onila			
2.3.3	Construction and Domestic Wastes	/	wash-out - numerous			
2.3.3	Construction and Domestic Wastes	/	weather - sed or ground			
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.	/	neather-sed or ground no acceptable Lacility			
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.					
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.					
2.4	Dewatering					
2.1	Discharge off site?	· Yes · No				
4	Self-Inspection Reports	a d	Latest Report Date:			
Notes: (City Inspector Use) Items in compliance can be left blank.						
<sup>1</sup> Construction General Permit (CGP) Maintenance or corrective actions are to be completed within 7 days.						
Notes:						

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov

City of Albuquerque Stormwater Inspector Signature and Date:

ta che 2-4-19
Signature Date