

## City of Albuquerque Stormwater Construction Site Inspection Report

			General Information			
Project Name and Location		Legacy Home Health Care  3610 Bosque Can NW  James Cargile ESC File No. #12E006F				
		3610 Bosque Can NW				
Site Contact Name & Agency		Jamie Cargile EB 505-379-4354		ESC File No. NPDES ID No.	£12£006F	
					NMR, 1000137	
Date of Inspection		1-18-19 Start/End Time 10:05/10:45				
COA Inspector Name		Curtis Cherne, Stormwater Quality				
Describe Present Phase of Construction		Constructing 616				
Type of I	nspection:		,			
• Regu	ılar • During storn	n event • Post-	-storm event (> 0.25 inch)	311 / Complaint Res	ponse • Follow-Up	
			Weather Information			
	at time of this inspection				perature: ~ 76 F°	
	lear Cloudy Ra	ain · Sleet		Windy		
Amount:			• Snow"	,		
			Inspection			
CGP <sup>1</sup> Section	BMP / Activity	Maintenance or Corrective Action Required		Location and Notes	5	
1.5	Post a Notice					
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft					
2.2.3	Sediment control along any perimeter		Sit force main		t 51 do	
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.4	Minimize sediment track-					

2.2.5	Manage stockpiles					
2.2.6	Minimize Dust					
2.2.10	Protect Storm Drain Inlets					
2.2.10	Protect Storm Drain Inlets					
2.2.11	Minimize erosion of conveyance channels					
2.2.12	Sediment Basins					
2.2.14	Stabilize exposed portions of the site.					
2.2.14	Stabilize exposed portions of the site.					
2.2.14	Stabilize exposed portions of the site.					
2.2.14	Stabilize exposed portions of the site.					
2.3.1	Equipment and Vehicle Fueling		8			
2.3.2	Equipment and Vehicle Washing					
2.3.3	Building Material Storage					
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage					
2.3.3	Construction and Domestic Wastes	$\sqrt{}$	trash east side and in pand			
2.3.3	Construction and Domestic Wastes					
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.	V	wash-out			
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.					
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.					
2.4	Dewatering					
2.1	Discharge off site?	· Yes · No				
4	Self-Inspection Reports	request	Latest Report Date: 12-14-18			
Notes: (City Inspector Use) Items in compliance can be left blank.  Construction General Permit (CGP)  Maintenance or corrective actions are to be completed within 7 days.						
jcargile debnm. com						

City of Albuquerque Stormwater Inspector Signature and Date:

| City of Albuquerque Stormwater Inspector Signature | Color |
| Signature | Date

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov