



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	O'Reilly Auto Parts				
Location:	6380 Corrs NW				
Site Contact Name & Agency	Robert Duncan Hutton Exchange	ESC File No.	E12E006G		
		NPDES Id. No.	NMR1001DT		
Inspection Date:	05/21/19	Start/End Time:	11:30/11:40		
CoA Stormwater Inspector:	Curtis Cherne				
Construction Phase:	landscaping				
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input checked="" type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Cloudy	Temperature: ~	55
Estimated date of last storm 0.25" or greater	5/10/2019		

Item Number	Deficiency/ Corrective Action		
2.1	Discharge off site? (Y/N)	no	
4	Self Inspection Reports		Latest report Date: 4/16/2019

Notes:	
All previous violations mitigated	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Curtis Cherne PE 505-924-3420
ccherne@cabq.gov 05/21/19 Curtis a Cherne