



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Homewood Suites		
Location:	5400 San Antonio		
Site Contact Name & Agency	Ken Wilt kwilt76@gmail.com	ESC File No.	E18E050
		NPDES Id. No.	NMR100158
Inspection Date:	05/03/19	Start/End Time:	1010/1030hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	Interior build out		
Type of Inspection:	☐ Regular	☐ Storm Event	☐ Post Storm Event >0.25" ☒ 311/Complaint ☒ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	67*
Estimated date of last storm 0.25" or greater	4/22/2019		

Item Number	Deficiency/ Corrective Action		
	No deficiencies noted		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date:

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 05/03/19