City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Homewood Suites						
Location:	5400 San Antonio						
Site Contact Name & Agency	Ken Wilt			ESC File No.	E18E050		
	kwilty76@gmail.com			NPDES Id. No.	NMR100158		
Inspection Date:	08/19/19	Start/End Time:	1150/1215hrs				
CoA Stormwater Inspector:		Timothy E. Sims					
Construction Phase:	STABILIZED						
Type of Inspection:	x Regular	Storm Event		Post Storm Event >0.25"		311/Complaint	Follow Up

Weather at time of inspection?	Clear	Temperature: ~	91*
Estimated date of last storm 0.25" or greater		7/7/2019	

Item Number	Deficiency/ Corrective Action			
	STABILIZED			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports		Latest report Date:	

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov 08/19/19