

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:		Homewood Suites					
Location:		5400 San Antonio					
Site Contact Name & Agency		Ken Wilt		ESC File No.		E18E050	
		kwilty76@gmail.com		NPDES Id. No.		NMR100158	
Inspection Date:		08/19/19		Start/End Time:		1150/1215hrs	
CoA Stormwater Inspector:		Timothy E. Sims					
Construction Phase:		STABILIZED					
Type of Inspection:	x	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up	

Weather at time of inspection?	Clear	Temperature: ~	91*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action		
	STABILIZED		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date:

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 08/19/19