







Engineer Stamp





Papaya Place

Receiving Waters and Critical Habitat: Rio Grande is located 5.8 miles to the West.

Impairments: E. coli, Dissolved Oxygen, PCBs in Fish Tissue, Water Temperature

Grade: Before and After 2%