



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	E19D025C2	Project Name:	Good 2 Go Store #333 Demolition		
NPDES Id. No.	N/A	Location:	7330 San Antonio Dr. NE		
7/1/2021	Owner	Contractor			
Operator	La Cueva Property, LLC	Emergency Environmental Services			
Contact name & title	Mike Petersen	Dan Kelley			
e-mail	mike.petersen@southforkmanagemen		dank@emergencyenv.com		
Contact Phone #			505-503-3884		
COA Inspector	Thomas Evans		Start/End Time:	1:15 PM-1:20 PM	
Construction Phase:	Demolition				
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"	311/Complaint Follow Up	
Weather at time of inspection?	clear		Temperature: ~	80	
Estimated date of last storm 0.25" or greater	6/28/2021				
Item Number	Deficiency/ Corrective Action				
1	None. All demolition activities are completed.				
2					
3	STABILIZED				
4					
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Received	Latest report Date:	7/1/2021	

Notes:	Wattles and silt fence will remain within the security fence.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Thomas Evans (505-803-6215) *Thomas Evans* 07/02/2021
tevans@cabq.gov