



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	E21E012X	Project Name:	Otero Residence
NPDES Id. No.	NMR1003FT	Location:	10601 San Antonio
5/28/2021	Owner	Contractor	
Operator	Compass Engineering and Construction Services, LLC.		
Contact name & title	Mark Otero		
e-mail	mark@compassnm.com		
Contact Phone #	505-221-6003		
COA Inspector	Thomas Evans	Start/End Time:	1:30 PM-1:35 PM
Construction Phase:	Home construction		
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"
		311/Complaint	Follow Up
Weather at time of inspection?		clear	Temperature: ~ 86
Estimated date of last storm 0.25" or greater		5/3/2021	
Item Number	Deficiency/ Corrective Action		
1	No posting of NOI permit coverage. Post signage of NOI permit coverage in a location visible to the public.		
2			
3			
4			
5			
2.1	Discharge off site? (Y/N)	no	
4	Self Inspection Reports	Requested	Latest report Date:

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Thomas Evans (505-803-6215) *Thomas Evans* 06/02/2021
tevans@cabq.gov