

CITY OF ALBUQUERQUE



April 5th, 2015

Kevin Patton
Pulte Homes
7601 Jefferson St NE
Albuquerque, NM 87109
Kevin.Patton@PulteGroup.com

**Re: Drainage Control Ordinance Violations for Erosion and Sediment Control-
Rinsing Street into Storm Drain System - Sevilla at Andalucia Subdivision**

Dear Mr. Patton,

On April 4th, 2016, a water truck was spraying water onto Calle Parasol St. The water picked up sediment and debris and transported them into the storm drain system in Calle Espana NW. Photos of the violation are included in this letter.

The activity of rinsing the street(s) is to cease. In addition, the inlet protection in Calle Espana was ineffective and should be evaluated.

If this activity is observed again after 30 days, Pulte Homes is subject to a fine up to \$500/day per the City's Drainage Control Ordinance.

PO Box 1293

Albuquerque

New Mexico 87103

www.cabq.gov



Water release location; 5001 Calle Parasol NW

CITY OF ALBUQUERQUE



Water was followed around the corner. This is the beginning of the hydrograph.

PO Box 1293

Albuquerque

New Mexico 87103

www.cabq.gov



Rinse water flowing into inlet in Calle Espana NW. Inlet protection not filtering water.

CITY OF ALBUQUERQUE



Close-up of rinse water. Water is not clean.

PO Box 1293

If you have any questions, you can contact me at 924-3420.

Albuquerque

Sincerely,

Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality
Planning Dept.

New Mexico 87103

www.cabq.gov

C: Michael@superiorstormwater.com