

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information												
Project Na	me:	Montgomery Church of Christ										
Location:		7201 Montgomery Blvd. NE										
Site Contact Name &		D. Mcall -		ESC File No.	F19E003A							
Agency		midwayleasing@comcast.n		NPDES Id. No.		NMR1002FA						
Inspection Date:		02/25/20	Start/End Time: 09	955/1030hrs								
	water Inspecto											
	ction Phase:				tical							
Type of I	nspection: x	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	Follow Up					
						•						
Weath	er at time of i	nspection? Clear storm 0.25" or greater		ar	Temperature: ~ 37*		3/*					
Estimated	date of last s	torm 0.25	or greater			11/22/2019						
Item	Deficiency/Corrective Action											
Number	Deficiency/ Corrective Action											
	no issues observed with this inspection											
	no issues observed with this inspection											
	***Please provide latest SWPPP self-inspection report											
2.1	Discharge off site?	(Y/N)	No									
4	Self Inspect	tion Reports	requested	Latest rep	oort Date:	1/23/20	020					

Notes:			

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155