

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Nan	ne:	Coors Village T	ract 3A-3B					
Location:		Coors and Western Trails						
Site Contact Name & Agency		James Jeppson- Presbyterian ESC File No. F11E019A						
		jjeppson@ph	ppson@phs.org NPDES Id. No. NMR10022T					
Inspection Date:		03/17/20 Start/End Time: 1030/1100hrs						
CoA Stormwater Inspector: Timothy E. Sims								
Construction Phase: STABILIZED								
Type of In	spection: x	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	Follow Up	
Weather at time of inspection? Cloudy Temperature: ~ 52*								
Estimated date of last storm 0.25" or greater								
Item								
Number	Deficiency/ Corrective Action							
Number								
	CTADILIZED							
	STABILIZED							
		017 (5121225						
2.4		(1.4.10.1)	N1 -	1				
	Discharge off site?	(Y/N)	No					
4	Self Inspect	ion Reports		Latest rep	ort Date:	2/13/20)20	
Notes:								

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

03/17/20____