

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Name:			Coors Village Tract 3A-3B						
Location:			Coors and Western Trails						
Site Contact Name &			James Jeppson- Presbyterian ESC File No. F11E019A						
Agency			jjeppson@phs.org NPDES Id. No. N					NMR10022T	
Inspection			10/22/19	Start/En	d Time: (0945/0955hrs			
CoA Stormwater Inspector: Timothy E. Sims									
	ction Phase:		utilities						
Type of Inspection: x			Regular	Storn	n Event	Post Storn	n Event >0.25"	311/Complaint	Follow Up
Weath	er at time o	of ir	nspection?		Cle	ear		rature: ~	33*
Estimated	date of las	st s	torm 0.25" c	or grea	ter		10/4/2019		
Item									
	Deficiency/ Corrective Action								
Number									
	no issues noted with this inspection								
2.1	Discharge off sit		(Y/N)		No	1			
4	Self Insp	ect	ion Reports			Latest r	eport Date:	10/22/2	019
Notes:									
				_					

 $\label{lem:city} \textbf{City of Albuquerque Stormwater Inspector Signature and date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

10/22/19 _____