



City of Albuquerque Stormwater Construction Site Inspection Report

General Information					
ESC File No.	F13E028A	Project Name:	Griegos Farms		
NPDES Id. No.	NMIR1005G7	Location:	1860 Griegos Rd NW		
5/7/2025	Owner	Contractor			
Operator	Griegos Farms, LLC	Guzman Construction Solutions			
Contact name & title	Jay Rembe	Tyler Richter			
e-mail	rembe@rembedesign.com	tyler@guzmancs.com			
Contact Phone #	505-453-7164	505-452-0663			
COA Inspector	Chancellor English	Start/End Time:	12:15pm		
Construction Phase:	Approximately half the structures are complete and stabilized				
Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?	Clear		Temperature: ~	60	
Estimated date of last storm 0.25" or greater	5/4/2025				
Item Number	Deficiency/ Corrective Action				
1	The SWPPP has not been certified by either operator (Griegos Farms, LLC or Guzman Construction Solutions) in violation of CGP Part 7.2.10. The self-inspection reports were not current in violation of CGP Part 4.7.3. Required mitigation: Your signatory must sign and date your SWPPP in accordance with Appendix G, Part G.11. You must keep a copy of all inspection reports at the site or at an easily accessible location so that they can be made immediately available during an on-site inspection per CGP Part 4.7.3.				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Yes	Latest report Date:	2/19/2025	

Notes:	
SWPPP in doc-box mounted on the back of posting. Trenches along the perimeter with block walls and basins throughout the site limit discharge from the site.	
Previous violations for washout, BMPs, and posting have been mitigated.	
A Delegation of Authority has not been completed by the Griegos Farms, LLC NOI certifier.	

City of Albuquerque Stormwater Inspector Signature and date: 5/8/2025
 Contact information: Chancellor English (505) 924-3325
cenglish@cabq.gov *Chancellor English*