

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No. F14E		021 Project Name:		Lowes	es Market #99 Dock and Storage addition			
NPDES Id. No.	NMR10044R		Location:	4701 4th ST NW				
8/4/2022		Owner			Contractor			
Operator		Lowes Pay and Save inc.						
Contact name & title		Shawn Pickrell						
e-mail		shawnp@lo	wesmarket.com					
Contact Phone #		806-786-0255						
COA Inspector		Doug Hughes			Start/End Time:	: 10:30am		
	tion Phase:	Staging						
Type of Inspection:		Regular	Storm Event	•	Event >0.25"	311/Complaint	Follow Up	
							80	
Estimated date of last storm 0.25" or greater 8/1/2022								
Item								
Number	Deficiency/ Corrective Action							
1	none							
_								
2								
3								
4								
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspection Report			Latest re	oort Date:	8/8/20	122	
4	Sell Hispec	tion reports		Latest le	Joil Date.	0/0/20	22	
Notes:								
Construction is nearly complete Landscaping is at 80% complete and a porta-potty needs removed.								
construction is nearly complete Euroscoping is at 60% complete and a porta potty needs removed.								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505-924-3420)

jhughes@cabq.gov

8/12/22 James D. Hughes