

### **INSPECTION REPORT**

# **GENERAL INFORMATION**

DATE OF INSPECTION:	5/24/2021
COMPANY NAME:	Troyer Homes, LLC
PROJECT NAME:	Bosque Escondido
LOCATION:	712 Montano Road NW,Albuquerque,New Mexico,87107
TRACKING NO:	NMR1003QT, NMR1003SI
COMPLIANCE EVALUATION:	Satisfactory
TYPE OF INSPECTION:	7Day
START TIME:	10:30 AM
END TIME:	10:50 AM
INSPECTOR'S NAME:	Diana Baltazar
INSPECTOR'S TITLE:	NPDES Inspector
INSPECTOR'S QUALIFICATIONS:	StormwaterONE No: 6f93e116
INSPECTOR'S CONTACT:	505-379-2445
PHASE OF CONSTRUCTION:	<ul> <li>□ Clear and Grub</li></ul>
WEA	ATHER INFORMATION

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?	Yes	<ul><li>No</li></ul>
WEATHER AT TIME OF THIS INSPECTION:	Clear	
TEMPERATURE:	70	
HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?	Yes	<ul><li>No</li></ul>
ARE ANY DISCHARGES OCCURRING NOW?	Yes	<ul><li>No</li></ul>
ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?	Yes	<ul><li>No</li></ul>

# POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	РНОТО
1	NPDES Permit Notification	None	None	Entrance	1	EA	
2	Silt Fence	None	None	Perimeter	1000	LF	

# **GENERAL SITE INSPECTION ITEMS**

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	● Yes ○ No ○ N/A	Yes No	Sign needs NPDES number printed and posted.
2	Are steep slope areas not actively being worked properly stabilized?	Yes No N/A	Yes No	
3	Are disturbed areas not actively being worked properly stabilized?	● Yes ○ No ○ N/A	Yes No	Areas are currently being worked on.
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	● Yes ○ No ○ N/A	Yes No	Silt fence surrounding site is intact.
5	Are discharge points and receiving waters free of any sediment deposits?	• Yes ONo ON/A	Yes • No	
6	Is trash/litter from work areas collected and placed in covered dumpsters?	● Yes ○ No ○ N/A	Yes No	Site is clean and clear of trash and litter.
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	Yes No N/A	Yes No	
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	○Yes ○No ●N/A	Yes No	
9	Are materials that are potential stormwater contaminants stored inside or in containers?	Yes No N/A	Yes • No	
10	Are offsite flows entering the construction site?	○Yes ● No ○ N/A	○Yes • No	
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	○Yes ● No ○ N/A	Yes No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	● Yes ○ No ○ N/A	○Yes • No	
13	Are non-stormwater discharges properly controlled?	● Yes ○ No ○ N/A	◯ Yes ● No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	• Yes ONo ON/A	◯ Yes ● No	
15	Are changes to the SWPPP necessary at this time?	○ Yes ● No ○ N/A	◯ Yes ● No	
16	Are dust control measures being properly implemented?	● Yes ○ No ○ N/A	◯ Yes ● No	
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	● Yes ○ No ○ N/A	○Yes ● No	

#### **CERTIFICATION AND SIGNATURE BY INSPECTOR**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY:	Diana Baltazar	DATE: May	y 25, 2021
---------------	----------------	-----------	------------

**SIGNATURE AND AFFILIATION:** 

#### **CERTIFICATION AND SIGNATURE BY PERMITTEE**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:	,	DATE:
CICNATURE.		