Enterprise Builders: Maverik on Montgomery



Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 06-16-2021 Time: 8:29 AM

Permit Tracking #: NMR1003I9 Inspector Name: Mario Alderete Qualifications: Inspector

Current Weather Conditions: Date and Amount of Last Recordable Storm Event: 05-31-2021 .5

Thunderstorms (Slight Chance)

Construction Time Line:

Construction Time Line:							
Action	Start Date	Date Complete					
Initial BMP Installation	01-11-2021	01-13-2021					
Clearing and Grubbing	01-11-2021						
Utility Installation							
Construction of Structure	01-27-2021						
Final Stabilization							

Site Walk:

Yes	No	N/A	Comment
\boxtimes			
\boxtimes			
\boxtimes			
		\boxtimes	
		\boxtimes	
\boxtimes			Water truck onsite
	\boxtimes		
X			
\boxtimes			
\boxtimes			
\boxtimes			
		\boxtimes	

Enterprise Builders: Maverik on Montgomery

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?	\boxtimes			Construction trailer
Was the SWPPP updated at the time of the inspection?				
Are all certification pages signed?	\boxtimes			
Are inspector qualifications in the SWPPP?	\boxtimes			
Is there a copy of the NOI and Acknowledgement letter?				
Is there a delegation letter in the SWPPP?	\boxtimes			
Was the last inspection/CAL certified?			\boxtimes	

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

casimicing raise intermation, includin	ig the pecchanity of the and implicational for informing violations.	
Owner:		
Name	Signature	Date
Operator: David Lundsten	DAZ	06-16-2021
Name	Signature	Date

Additional Comments:

Enterprise Builders: Maverik on Montgomery



Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
North west entrance	Corrective Action	Street needs to be swept	06-16-2021		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector: Joshua Armijo 06-16-2021

Name Signature Date

Site Walk Deficiency Photos - North west entrance



1-13-21 kk





1-27-21



2/17/21



2/24/21






3/10/21



3/17/21



3/17/21



3/24/21



3/31/21





4/14/21



4/21/21



4/28/21





5/12/21



5/26/21



6/2/21





6-16-21