



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Montgomery Church of Christ				
Location:	7201 Montgomery Blvd. NE				
Site Contact Name & Agency	D. Mcall - midwayleasing@comcast.net	ESC File No.	F16E003A		
		NPDES Id. No.	NMR1002FA		
Inspection Date:	11/25/19	Start/End Time:	1335/1345hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	earthwork				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	57*
Estimated date of last storm 0.25" or greater	11/22/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 11/19/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 11/25/19