



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

ESC File No.	F16E003B1	Project Name:	Curia New Mexico
NPDES Id. No.	NMRT005OE	Location:	4401 Alexander Blvd NE
6/14/2024	Owner	Contractor	
Operator	Curia New Mexico	BE&K Builders Group LLC	
Contact name & title	Jonathan Shoemaker	Norm Colton	
e-mail	<a href="mailto:jon.shoemaker@curiaglobal.com">jon.shoemaker@curiaglobal.com</a>	<a href="mailto:norm.colton@bekbg.com">norm.colton@bekbg.com</a>	
Contact Phone #	224-551-9187	732-606-6911	
COA Inspector	Chancellor English	Start/End Time:	1pm
Construction Phase:	verticals		
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" <input type="checkbox"/> 311/Complaint <input type="checkbox"/> Follow Up
Weather at time of inspection?	Clear	Temperature: ~	95
Estimated date of last storm 0.25" or greater	6/10/2024		
Item Number	Deficiency/ Corrective Action		
1	None		
2.1	Discharge off site? (Y/N)	no	
4	Self Inspection Reports	Yes	Latest report Date: 6/5/2024

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: 6/18/2024  
Contact information: Chancellor English (505) 924-3325  
[english@cabq.gov](mailto:english@cabq.gov)

*Chancellor English*