

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.					Curia New Mexico		
NPDES Id. No. NMR10				4401 Alexander Blvd NE			
5/14/2025		Owner		Contractor			
Operator		Curia New Mexico			BE&K Builders Group LLC		
Contact name & title		Jonathan Shoemaker			Norm Colton		
e-mail		jon.shoemaker@curiaglobal.com			norm.colton@bekbg.com		
Contact Phone #		224-551-9187			732-606-6911		
COA Inspector		Chancellor English			Start/End Time: 2pm		
Construction Phase:					erior		
Type of Inspection:		Regular	Storm Event	•		311/Complaint	Follow Up
Weather at time of i		<u>'</u>		ar	Temperature: ~ 75		
Estimated date of last storm 0.25" or greater 5/4/2025							
Item	Deficiency/ Corrective Action						
Number	Denoteriory, corrective riodon						
1	None						
				_			
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspect	tion Reports	Yes	Latest rep	oort Date:	4/23/20	)25
Notes:							
Most of the site is still paved but covered in sediment. Stormwater discharges into a pond on the north							
side of the site.							
The track-out pad at the construction entrance is near capacity of sediment.							
,							

City of Albuquerque Stormwater Inspector Signature and date: 5/14/2025

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov

Chancellor English