



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	F16E011	Project Name:	NM JATC Building Addition		
NPDES Id. No.	NMR1002ZB	Location:	4501 Montbel Pl. NE		
5/20/2021	Owner	Contractor			
Operator	NM JATC for the Electrical Industry		Summit Construction		
Contact name & title	Charles Humiston		Ed Fuller		
e-mail	director@nmjatc.org		ed@summitconstr.com		
Contact Phone #	505-341-4444		505-239-4824		
COA Inspector	Thomas Evans		Start/End Time:	2:45 PM/3:05 PM	
Construction Phase:	Final Stabilization				
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?	clear		Temperature:	~ 86	
Estimated date of last storm 0.25" or greater	5/3/2021				
Item Number	Deficiency/ Corrective Action				
1	No posting of NOI. Re-post signage of NOI permit coverage in a location clearly visible to the public.				
2	Re-establish permitter BMPs for erosion and sediment control.				
3					
4					
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:	none on file	

Notes:	Per Ed Fuller, hydro-seed was applied 3 weeks ago across the site. Hydro-mulch was applied today. They removed their posting of permit coverage, and I directed them to re-post it.

City of Albuquerque Stormwater Inspector Signature and date:
 Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 05/24/2021