



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	F16E014C	Project Name:	ABCWUA Customer Service and Operations		
NPDES Id. No.	NMR10027A	Location:	6000 Alexander Blvd. NE		
5/4/2021	Owner	Contractor			
Operator	ABCWUA	Bradbury Stamm			
Contact name & title	Scott Salvas	Eloy Apodaca			
e-mail	ssalvas@abcwua.org	eapodaca@bradburystamm.com			
Contact Phone #	505-230-2344	505-259-8576			
COA Inspector	Thomas Evans	Start/End Time:	3:20 PM/3:45 PM		
Construction Phase:	Stabilization				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Past Storm Event >0.25"	☐ 311/Complaint	
Weather at time of inspection?		clear	Temperature: ~	74	
Estimated date of last storm 0.25" or greater		5/3/2021			
Item Number	Deficiency/ Corrective Action				
1	Disturbed slopes at the pond do not appear to be stabilized. Abide by stabilization requirements set forth in CGP 2.2.14				
2	No posting of permit coverage.				
3					
4					
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:	7/30/2020	

Notes:	Rocks and mulch are stabilization controls being used.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 05/05/2021