Bradbury Stamm: ABCWUA - Customer Service and Operations Facilities



Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 02-25-2020 Time: 2:38 PM

Permit Tracking #: NMR10025I Inspector Name: Carlos Flores Qualifications: CISEC

Current Weather Conditions: clear Date and Amount of Last Recordable Storm Event: 11-21-2019 1"

Construction Time Line:

Action	Start Date	Date Complete
Initial BMP Installation		
Clearing and Grubbing		
Utility Installation		
Construction of Structure		
Final Stabilization		

Site Walk

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			
Are areas that have been disturbed, but not under construction been properly stabilized?			\boxtimes	
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.			\boxtimes	
Silt Fence	\boxtimes			
Wattles/Filter Sock	\boxtimes			
Inlet Protection	\boxtimes			
Cut Back Curbs			\boxtimes	
Waste Management	\boxtimes			
Vehicle Tracking Control	\boxtimes			new rock installed
Material Storage			\boxtimes	
Dust Control	\boxtimes			
Street Sweeping		\boxtimes		sweep street if needed for trackout
Construction Washouts i.e. Concrete, Paint, Stucco Etc.				
Discharge Points	\boxtimes			
Sanitary Stations	X			
Stockpiles	X			stockpiles are being activly used
Other			\boxtimes	Perimeter site check

Bradbury Stamm

NMR10025I

Date

Bradbury Stamm: ABCWUA - Customer Service and Operations Facilities

SWPPP Information:

Question		Yes	NO	N/A	Comment		
Is the SWPPP kept on site?		\boxtimes					
Was the SWPPP updated at the time inspection?	of the	\boxtimes					
Are all certification pages signed?		\boxtimes					
Are inspector qualifications in the SW	PPP?	\boxtimes					
Is there a copy of the NOI and Acknowletter?	wledgement	\boxtimes					
Is there a delegation letter in the SWF	PP?	\boxtimes					
Was the last inspection/CAL certified	?			\boxtimes			
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualifie personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations." Owner: ABCWUA							
Name	Signature				Date		
Operator: Floy anodaca	M	Λ.			02-26-2020		

Name Additional Comments:

Signature

Bradbury Stamm: ABCWUA - Customer Service and Operations Facilities



Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
Sweep street - Mission	Maintenance	Sweep street for sediment	11-12-2019		
CWO area - Washout on ground	Maintenance	Clean up washout from ground, Check bin for leaks.	02-18-2020		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector:	Carlos Flores	02-25-2020	
_	Name	Signature	Date